



[4910-13-P]

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2016-4233; Directorate Identifier 2016-CE-003-AD]

RIN 2120-AA64

Airworthiness Directives; BLANIK LIMITED Gliders

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: We propose to adopt a new airworthiness directive (AD) for BLANIK LIMITED Models L-13 Blanik and L-13 AC Blanik gliders (type certificate previously by LET Aeronautical Works) that would supersede AD 99-19-33. This proposed AD results from mandatory continuing airworthiness information (MCAI) originated by an aviation authority of another country to identify and correct an unsafe condition on an aviation product. The MCAI describes the unsafe condition as lack of distinct color marking of the elevator drive. We are issuing this proposed AD to require actions to address the unsafe condition on these products.

DATES: We must receive comments on this proposed AD by [INSERT DATE 45 DAYS AFTER DATE OF PUBLICATION IN THE FEDERAL REGISTER].

ADDRESSES: You may send comments by any of the following methods:

- Federal eRulemaking Portal: Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.
- Fax: (202) 493-2251.

- Mail: U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue, SE, Washington, DC 20590.

- Hand Delivery: U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue, SE., Washington, DC 20590, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this proposed AD, contact BLANIK LIMITED , 2nd Floor Beaux Lane House, Mercer Street Lower, Dublin 2, Republic of Ireland; phone: +420 733 662 194; email: info@blanik.aero; Internet: http://www.blanik.aero/%EF%BB%BFcustomer_support. You may review this referenced service information at the FAA, Small Airplane Directorate, 901 Locust, Kansas City, Missouri 64106. For information on the availability of this material at the FAA, call (816) 329-4148.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2016-4233; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this proposed AD, the regulatory evaluation, any comments received, and other information. The street address for the Docket Office (telephone (800) 647-5527) is in the ADDRESSES section. Comments will be available in the AD docket shortly after receipt.

FOR FURTHER INFORMATION CONTACT: Jim Rutherford, Aerospace Engineer, FAA, Small Airplane Directorate, 901 Locust, Room 301, Kansas City, Missouri 64106; telephone: (816) 329-4165; fax: (816) 329-4090; email: jim.rutherford@faa.gov.

SUPPLEMENTARY INFORMATION:

Comments Invited

We invite you to send any written relevant data, views, or arguments about this proposed AD. Send your comments to an address listed under the ADDRESSES section. Include “Docket No. FAA-2016-4233; Directorate Identifier 2016-CE-003-AD” at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of this proposed AD. We will consider all comments received by the closing date and may amend this proposed AD because of those comments.

We will post all comments we receive, without change, to <http://regulations.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact we receive about this proposed AD.

Discussion

On November 8, 1999, we issued AD 99-19-33, Amendment 39-11320 (64 FR 50440; September 17, 1999) (“99-19-33”). That AD required actions intended to address an unsafe condition on BLANIK LIMITED Models L-13 Blanik gliders and was based on mandatory continuing airworthiness information (MCAI) originated by the Civil Aviation Authority, which is the aviation authority for the Czech Republic. That MCAI (AD CAA-AD-4-099/98, dated December 30, 1998) was issued to correct an unsafe condition for EVECTOR, spol. s.r.o. Models L 13 SEH VIVAT and L 13 SDM VIVAT gliders and BLANIK LIMITED Models L-13 Blanik and L-13 AC Blanik gliders. The MCAI states:

Colour marking of elevator drive is not inspected or re-painted during sailplane operation. The elevator drive is asymmetrical and improper installation causes significant elevator deflection changes.

You may examine the MCAI on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2016-4233.

A review of records since issuance of AD 99-19-33 revealed that the FAA inadvertently did not address this MCAI for the EVECTOR, spol. s.r.o. Models L 13 SEH VIVAT and L 13 SDM VIVAT gliders and the BLANIK LIMITED Model L-13 AC Blanik gliders. This proposed AD would supersede AD 99-19-13 to add the BLANIK LIMITED Model L-13 AC Blanik gliders to the applicability of the AD.

The FAA will address the EVECTOR, spol. s.r.o. Models L 13 SEH VIVAT and L 13 SDM VIVAT gliders in another AD action.

Related Service Information under 1 CFR part 51

LET Aeronautical Works has issued LET Mandatory Bulletin MB No.: L13/082a, dated December 10, 1998. The service information describes procedures for painting the left arm of the elevator drive. This service information is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the ADDRESSES section of this NPRM.

FAA's Determination and Requirements of the Proposed AD

This product has been approved by the aviation authority of another country, and is approved for operation in the United States. Pursuant to our bilateral agreement with this State of Design Authority, they have notified us of the unsafe condition described in the MCAI and service information referenced above. We are proposing this AD because we evaluated all information and determined the unsafe condition exists and is likely to exist or develop on other products of the same type design.

Costs of Compliance

We estimate that this proposed AD will affect 124 products of U.S. registry. We also estimate that it would take about 1 work-hour per product to comply with the basic requirements of this proposed AD. The average labor rate is \$85 per work-hour. Required parts would cost about \$10 per product.

Based on these figures, we estimate the cost of the proposed AD on U.S. operators to be \$11,780, or \$95 per product.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. "Subtitle VII: Aviation Programs," describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in "Subtitle VII, Part A, Subpart III, Section 44701: General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

We determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

- (1) Is not a “significant regulatory action” under Executive Order 12866,
- (2) Is not a “significant rule” under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979),
- (3) Will not affect intrastate aviation in Alaska, and
- (4) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39 - AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The FAA amends § 39.13 by removing Amendment 39-11320 (64 FR 50440; September 17, 1999), and adding the following new AD:

BLANIK LIMITED: Docket No. FAA-2016-4233; Directorate Identifier 2016-CE-003-AD.

(a) Comments Due Date

We must receive comments by [INSERT DATE 45 DAYS AFTER DATE OF PUBLICATION IN THE FEDERAL REGISTER].

(b) Affected ADs

This AD replaces AD 99-19-33, Amendment 39-11320 (64 FR 50440; September 17, 1999) (“AD 99-19-33”).

(c) Applicability

This AD applies to BLANIK LIMITED Models L-13 Blanik and L-13 AC Blanik gliders (type certificate previously by LET Aeronautical Works), all serial numbers, certificated in any category.

(d) Subject

Air Transport Association of America (ATA) Code 27: Flight Controls.

(e) Reason

This AD was prompted by mandatory continuing airworthiness information (MCAI) originated by an aviation authority of another country to identify and correct an unsafe condition on an aviation product. The MCAI describes the unsafe condition as lack of distinct color marking of the elevator drive. We are issuing this AD to prevent inadvertent backward installation of the elevator drive, which could cause significant elevator deflection changes and lead to loss of control.

(f) Actions and Compliance

Unless already done, do the following actions in paragraphs (f)(1) and (f)(2) of this AD, including all subparagraphs:

(1) Model L-13 Blanik gliders:

(i) Within the next 3 calendar months after November 8, 1999 (the effective date retained from AD 99-19-33), paint the elevator drive mechanism using a contrasting color (such as red) following the procedures in LET Mandatory Bulletin MB No.: L13/082a, dated December 10, 1998.

(ii) As of November 8, 1999 (the effective date retained from AD 99-19-33), only install an elevator bellcrank that has been painted as specified in paragraph (f)(1)(i) of this AD and that has been properly oriented to make sure it is not being installed backward.

(2) Model L-13 AC Blanik gliders:

(i) Within the next 3 calendar months after the effective date of this AD, paint the elevator drive mechanism using a contrasting color (such as red) following the procedures in LET Mandatory Bulletin MB No.: L13/082a, dated December 10, 1998.

(ii) As of the effective date of this AD, only install an elevator bellcrank that has been painted as specified in paragraph (f)(2)(i) of this AD and that has been properly oriented to make sure it is not being installed backward.

(g) **Other FAA AD Provisions**

The following provisions also apply to this AD:

(1) **Alternative Methods of Compliance (AMOCs):** The Manager, Standards Office, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. Send information to ATTN: Jim Rutherford, Aerospace Engineer, FAA, Small Airplane Directorate, 901 Locust, Room 301, Kansas City, Missouri 64106; telephone: (816) 329-4165; fax: (816) 329-4090; email: jim.rutherford@faa.gov. Before using any approved AMOC on any airplane to which the AMOC applies, notify your appropriate principal inspector (PI) in the FAA Flight Standards District Office (FSDO), or lacking a PI, your local FSDO.

(2) **Airworthy Product:** For any requirement in this AD to obtain corrective actions from a manufacturer or other source, use these actions if they are FAA-approved. Corrective actions are considered FAA-approved if they are approved by the State of Design Authority (or their delegated agent). You are required to assure the product is airworthy before it is returned to service.

(h) Related Information

Refer to MCAI Civil Aviation Authority AD CAA-AD-4-099/98, dated December 30, 1998, for related information. You may examine the MCAI on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2016-4233. For service information related to this AD, contact BLANIK LIMITED, 2nd Floor Beaux Lane House, Mercer Street Lower, Dublin 2, Republic of Ireland; phone: +420 733 662 194; email: info@blanik.aero; Internet: http://www.blanik.aero/%EF%BB%BFcustomer_support. You may review this referenced service information at the FAA, Small Airplane Directorate, 901 Locust, Kansas City, Missouri 64106. For information on the availability of this material at the FAA, call (816) 329-4148.

Issued in Kansas City, Missouri, on February 24, 2016.

Robert P. Busto,
Acting Manager, Small Airplane Directorate,
Aircraft Certification Service.

[FR Doc. 2016-04542 Filed: 3/3/2016 8:45 am; Publication Date: 3/4/2016]